

# Rotabroach<sup>®</sup> ELEMENT 40

Motorizzato a benzina

?

Per la manutenzione di alberi motore di motori di macchine agricole

?

Per la manutenzione di alberi motore di motori di macchine agricole

?



?

Rotabroach<sup>®</sup>

Per la manutenzione di alberi motore di motori di macchine agricole

Per la manutenzione di alberi motore di motori di macchine agricole

Per la manutenzione di alberi motore di motori di macchine agricole

Per la manutenzione di alberi motore di motori di macchine agricole

Per la manutenzione di alberi motore di motori di macchine agricole

?

Per la manutenzione di alberi motore di motori di macchine agricole

Per la manutenzione di alberi motore di motori di macchine agricole

Per la manutenzione di alberi motore di motori di macchine agricole

Per la manutenzione di alberi motore di motori di macchine agricole

?

?

?

?

?

2021 2022 2023 2024 2025 2026 2027 2028 2029 2030

2031 2032 2033 2034 2035 2036 2037 2038 2039 2040

?

2041 2042 2043 2044 2045 2046 2047 2048 2049 2050

?

?



?

?

2051 2052 2053 2054 2055 2056 2057 2058 2059 2060

?

?

?

?

?

?

?

?

?

?

?

?

?

?

?

?



?

Rb 2) 2223622  
 hb 2) 252 32 2723822  
 kb 2) 2251 2) 22 222n1 2222  
 W 2322222 2) 22  
 vb 2) 3252 2) 2 22 2723522228522  
 wb 2) 3252 2) 22 6752222) 22  
 Db 2) 752 22 2223252 2) 2  
 Fb 222 2222222) 2  
 Tb 2) 2) 222222222) 2  
 Rxb 2) 2) 62) 22 222222222) 2  
 RRb 2) 28) 2) 222228722522  
 Rhb 22 62) 223252 2) 2  
 Rkb 221 222262252 222 2) 222522221 22  
 RW 2) 22) 2222 22 2  
 Rvb 2) 3222222220 222221 32222 2) 2) 222  
 Rwb 2) 3222222220 222222 221 2) 22 222 22252) 222  
 RD 2) 752 22 2222 222 22222  
 RF 22222 2) 2222222222222222  
 RT 2) 222) 222 222 8222  
 hxb 2) 2) 2) 2222 222222 2) 2) 2) 2) 2) 2)  
 hRb 225282222 222) 22  
 hhb 228722522222222) 222222222 222222222 2) 2) 2) 2)  
 hkb 22 2) 22 2) 2)

V2  
 V2  
 v2  
 w2  
 D2  
 D2  
 F2  
 T2  
 T2  
 Rx2  
 Rx2  
 Rx2  
 RR2  
 Rh2  
 Rk2  
 Rv2  
 RD2  
 RF2  
 RT2  
 hR2  
 hh2  
 hk2

?  
 ?  
 ?  
 ?  
 ?  
 ?  
 ?  
 ?  
 ?

2222	2222 2222 2222 2222 2222 2222 2222 2222
2222 WkT2	22 2222222 2
2222 VxFF2	W 1 2222222222 22222222 2) 22222
2222 WRvh2	k1 1 2222 2) 22222
2222 kkRvk2	2222 8222222 7222
2222 WxTT2	2222 82222
2222 kRxv2	22 2222 62222
2222 kxww2	22 22) 222222 222222 222


?  
 ?  
 ?  
 ?  
 ?  
 ?














**RSdb 2021**  
2021 2021 2021 2021  
7 2021 2021 2021 2021  
0 2021 2021 2021 2021




**LS7 2021 2021**  
2021 2021 2021 2021  
2021 2021 2021 2021  
2021 2021 2021 2021  
2021 2021 2021 2021




**I S7 dadrnb g2a 2021**  
2021 2021 2021 2021  
2021 2021 2021 2021  
1 2021 2021 2021 2021



**V67 dadrnb 2021**  
2021 2021 2021 2021  
7 2021 2021 2021 2021  
2021 2021 2021 2021




**kS7 Noog M 2021**  
2021 2021 2021 2021  
2021 2021 2021 2021  
9 2021 2021 2021 2021



**f S7 dadrnb 2021**  
2021 2021 2021 2021  
60 2021 2021 2021 2021  
1 2021 2021 2021 2021  
60 2021 2021 2021 2021

2021 2021) 2021 2021



**2021 2021 2021**  
2021 2021 2021 2021  
7 2021 2021 2021 2021  
23 2021 2021 2021 2021  
3 2021 2021 2021 2021



**2021 2021 2021**  
2021 2021 2021 2021  
3 2021 2021 2021 2021  
2021 2021 2021 2021



**2021 2021 2021**  
2021 2021 2021 2021  
Pl. 1 2021 2021 2021 2021  
1 8 2021 2021 2021 2021  
7 2021 2021 2021 2021  
2021 2021 2021 2021

2021 2021) 2021 2021

2021 2021 2021 2021 2021 2021 2021 2021  
1 2021 2021 2021 2021 2021 2021 2021  
2021 2021 2021 2021 2021 2021 2021  
2021 2021 2021 2021 2021 2021 2021  
2021 2021 2021 2021 2021 2021 2021

2021 2021 2021 2021 2021 2021 2021  
2021 2021 2021 2021 2021 2021 2021  
2021 2021 2021 2021 2021 2021 2021  
2021 2021 2021 2021 2021 2021 2021



2

US 2021 2022 2023 2024 2025 2026 2027 2028 2029 2030

2

2021 2022 2023 2024 2025 2026 2027 2028 2029 2030 2031 2032 2033 2034 2035 2036 2037 2038 2039 2040 2041 2042 2043 2044 2045 2046 2047 2048 2049 2050

2

2021 2022 2023 2024 2025 2026 2027 2028 2029 2030 2031 2032 2033 2034 2035 2036 2037 2038 2039 2040 2041 2042 2043 2044 2045 2046 2047 2048 2049 2050

2

2

2

2

2

2

2

2

2

2

2

2

2

2

2

2

2

2

2

2

2

2

2

2

2

2

2

2

2

2

2

2

2

2

2

2

2

2

2

2

2

2

2

2

2

2

2

2

2



2

2

2

2

2



2021 2022 2023 2024 2025 2026 2027 2028 2029 2030 2031 2032 2033 2034 2035 2036 2037 2038 2039 2040 2041 2042 2043 2044 2045 2046 2047 2048 2049 2050

2021 2022 2023 2024 2025 2026 2027 2028 2029 2030 2031 2032 2033 2034 2035 2036 2037 2038 2039 2040 2041 2042 2043 2044 2045 2046 2047 2048 2049 2050

KS 2021 2022 2023 2024 2025 2026 2027 2028 2029 2030


2

2021 2022 2023 2024 2025 2026 2027 2028 2029 2030 2031 2032 2033 2034 2035 2036 2037 2038 2039 2040 2041 2042 2043 2044 2045 2046 2047 2048 2049 2050

2

2021 2022 2023 2024 2025 2026 2027 2028 2029 2030 2031 2032 2033 2034 2035 2036 2037 2038 2039 2040 2041 2042 2043 2044 2045 2046 2047 2048 2049 2050

2



2

2021 2022 2023 2024 2025 2026 2027 2028 2029 2030 2031 2032 2033 2034 2035 2036 2037 2038 2039 2040 2041 2042 2043 2044 2045 2046 2047 2048 2049 2050


- 2
- 2
- 2
- 2







2






R0	00 VKRkR0	00500 00 v0RkR000000000	h0
h0	00 Vwx D0	0 v00000 06 050	h0
k0	000 kxkh0	0 8050068332570	R0
V0	000 kxkR0	000000 0) 000	R0
v0	000 Vhx R0	00500 00 V0RkR000000000	h0
w0	000 kxk D0	0001 0) 7000 80500	R0
D0	000 hxh0RpRRx0 000000000 hxh0k0phkx0 00	0 2725006601 000	R0
F0	00 VwhV0	0 0000000000 0000kvRw0	R0
T0	000 kxRk0	00050 0005000000	R0
Rx0	000 kxRRoRpRRx0 000000000 kxRRok0phkx0 00	0 00) 070	R0
RR0	00 Vx DF0	0 F00 06 050	h0
Rh0	00 Vx DT0	0 F00350 000 06 050	h0
Rk0	00 Vx DD0	00500 00 F0RkR000000000	h0
RV0	00 Vhx D0	0350 000 06 050	V0
Rv0	00 Vx TF0	00500 00 w0RkR000000000	V0
Rw0	000 Vx xv0	0000000086 0	R0
RD0	000 Vx hR0	00500 00 V0RkR000000000	RD0
RF0	000 kxx R0	0 00) 0 2800 00	R0
RT0	00 Vwhh0	07500 700 0	h0
hx0	000 kxhv0	000 70000000) 000	R0
hR0	00 VKRh0	0 580000500 00 w0RkR0	v0
hh0	000 kxTh0	086 0	h0
hk0	000 Vx xv0	003670) 00 06 050	h0
hW	000 Vx xW	000000	h
hv0	000 hxh V0	0220) 7002700006601 000	R0
hw0	000 Vx hT0	00500 00 w0RkR000000000	R0
hD0	000 kR xv0	0 00068332570500	R0
hF0	000 kxk F0	0 000700000000000 1 0	R0
hT0	000 kxkv0	000000	R0
kx0	00 Vx Th0	0 v00 00003522000 06 050	V0
kR0	00 Vx TR0	00500 00 v0RkR000000000	V0
kh0	000 kxh D0	000000	R0
kk0	000 kxk D0	0 000700000000000 1 0	R0
kV0	000 hxRk0	0 700) 000 00) 0	R0
kv0	000 Vhx V0	00500 00 k0RkR000000000	F0
kW0	000 Vhx v0	0 k00 870	V0
kD0	000 kxVW0	000000 00) 007000 1 0) 70	h0
kF0	000 Vhx w0	00500 00 V0RkR000000000	h0
kT0	000 vxx F0	0 0) 00000 00500	R0
Vk0	00 Vhx v0	00500 00 w0RkR000000000	h0
VR0	00 Vx wT0	0 V00 06 050	R0
Vh0	00 Vx wF0	0 V0 870	h0
Vk0	00 Vwx V0	0057 000000	R0
VW0	000 kxhw0	000700000000) 000	R0
Vw0	000 kxRh0	003670) 000 000	R0
Vw0	00 VKRRD0	000000001 30	R0
VD0	000 Vhx D0	00500 00 V0RkR000000000	h0
VF0	000 hx xF0	003670) 0051 0	k0
VT0	000 kxRv0	003670) 00800	R0
vx0	000 hxhx0RpRRx0 000000000 hxhx0k0phkx0 00	000006601 000	R0
vR0	000 hxh0DoRpRRx0 000000000 hxh0k0phkx0 00	02) 700000) 0006601 000	R0
vh0	000 kxDR0RpRRx0 000000000 kxDR0phkx0 00	020 0000 2500	R0
vk0	00 VKhT0	000000000000	R0
vV0	00 Vx FF0	V0 1 0 0) 000) 00000) 000	R0
vv0	00 Vx TT0	0 8000	R0
vw0	000 kxRvk0	0 800000003 7050	R0
vD0	000 kR xv0	00000000066000	R0
vF0	00 VRvh0	k1 1 0 0) 000) 00000) 000	R0



2029 2030 2031 2032 2033 2034

DrR	Vkv	P543	R
Drh	kvV	877) )	R
Drk	kRRF	35) )	R
DrV	kkRvv	5225	R
Drv	Vkw	5822520 FHF	v
Drw	kxhx	522563) )	R
DrD	VkxV	R67)	h
DrF	VkkD	682220 )	R
DrT	kxxv	22521 )	R
DrRx	VwRV	752) 7) )	R
DrRR	VxF	35) )	R
DrRh	kxxk	225225	R
DrRk	Vxv	2252252 V6 2822522	R
DrRV	Vxk	233) 22520 WFWV	V
DrRv	VxR	222225) 22) xFRx	k
DrRw	Vxh	26 25	h
DrRD	kxV	2222252R2Rrhv) Rv) kx)	R
DrRF	kxV	RD227 )	R
DrRT	kxxv	2222252VFWVW	R
Drhx	kxV	2252) )	R
DrhR	RDRV	2) ) 225) ) Vw F	R
Drhh	hxhh	8222252	R
Drhk	kxV	2252) )	R
DrhV	kxV	2222252	R
Drhv	VxV	2252 22) 26 25Rx 1 1 )	R
Drhw	Vxv	2222252) 22) Rx Rx	R
DrhD	hxRx	2252252 22)	R
DrhF	Vkxv	2) ) 225) ) Vw xk)	h
DrhT	Vkxv	P543	R
Drkx	hxRF	5922252661 )	R
DrkR	VkRx	P543	R
Drkh	kxkR	R222225272)	R
Drkk	kxxv	2252 272)	R
DrkV	Vvhh	2) ) 225) ) Vw xR)	R
Drkv	kxwR)RRx) )kxw)k)kx) )	51 7852)	R
Drkw	Vwxk	2) ) 225) ) Vw T)	R
DrkD	kxV	225) ) 222292)	R
DrkF	vxxV	222225272)	R
DrkT	Vkwhv	233) 22520 WFWV	h
DrV	kxwR)RRx) )kxwR)k)kx) )	2222252 Re	R
DrVR	kxwv	2222252 P52)	h
DrVh	kxwF	2 27252 P52)	R
DrVk	vxxh	2 27252 286) )	R
DrVV	vxxRF	2 P5221 229252	R
DrV	kxV	232227252	R
DrVw	kvwRD	251 ) )	h
DrVD	VwRk	22520 kFW) ) )	V
DrVF	VkV	233) 22520 WFWV	V
DrVT	kwRw	586 223	h
Drvx	kxwv	22522) 586 )	h
DrvR	kwRV	586 2 22)	h
Drvh	vxxk	232232	R
Drvk	Vkv	233) 22520 WFWV R)h	h





R	WvR	272570 P	R
h	Wvh	272570 P	R
k	Wvx	770 P	R
W	Wvk		R
v	WvV	57) 777	R
w	Wkw	250 k Rh	h
D	kxhF	2) 752 295	R
F	kRx	2) 752 7	R
T	WRT	ne) 3775	h
Rx	Wvv	55n725	R
RR	Wxv	k 87	h
Rh	WvD	2) ) 77) 77	R
Rk	Wvw	2) ) 77) 77	R





**Magnetic base** – before every operation the magnetic base should be checked to make sure that the base is flat and there is no damage present. An uneven magnet base will cause the magnet not to hold as efficiently and may cause injury to the operator.

**Adjustment of slide and bearing bracket alignment.**

An essential requirement of the machine is that the slide can move in a smooth and controlled manner, free of lateral movement and vibration.

This situation can be maintained by periodic adjustment of the slide and is accomplished in the following manner:

1. Place the machine in an upright position and, by means of the capstan, raise the slide to its highest position. Clean the brass gib strips and apply a small amount of light machine oil to the wear surfaces.
2. Now lower the slide back to its lowest position. Bring the slide into the center of the dovetail slide housing and loosen screws thus allowing free movement of the arbor support bracket.
3. Commencing with the middle screws, gently feed in all the screws until slight resistance is encountered.
4. Operate the slide up and down a few times to test the movement and make any further necessary adjustments. Try to ensure that all the screws are exerting a uniform pressure on the slide from top to bottom. A perfectly adjusted slide will operate freely up and down without any sideways movement.
5. Now raise the slide to its highest position. Slightly undo the arbor bearing bracket and, using fingers only, tighten the screws.
6. Place the machine on a steel plate, connect to power supply and switch on the magnet. Start up the motor. If the arbor is incorrectly aligned, the arbor support bracket will be seen to oscillate. Make any necessary further adjustments to the bracket to ensure correct alignment of the spindle and finally tighten the screws using a spanner. Lastly tighten the arbor bearing bracket.

**Check machines grease.**

The gearbox grease should be checked once a month to ensure all moving components are covered to prevent wear. The grease should be changed at least once a year to ensure you gain the best from your machine.

**Check Armature of the machine.**

This should be checked at least once a month to check that there are no visual signs of damage to the body or to the commutator. Some signs of wear will be seen on the commutator over a period of time but this is normal (this is the part that comes into contact with the brushes) however, if there are any signs of abnormal damage the part should be replaced.





- ?
- ?
- ?

Material	Material Hardness	Cutter
Mild and free cutting steels	<700N/mm <sup>2</sup>	RAP or RAPL
Mild and free cutting steels	<850N/mm <sup>2</sup>	SRCV or SRCVL
Steel angle and joists	<700N/mm <sup>2</sup>	RAP or RAPL
Steel angle and joists	<850N/mm <sup>2</sup>	SRCV or SRCVL
Plate and sheet steel	<700N/mm <sup>2</sup>	RAP or RAPL
Plate and sheet steel	<850N/mm <sup>2</sup>	SRCV or SRCVL
Aluminium	<750Nmm <sup>2</sup>	RAP or RAPL
Aluminium	<850N/mm <sup>2</sup>	SRCV or SRCVL
Brass	<700N/mm <sup>2</sup>	RAP or RAPL
Brass	<850N/mm <sup>2</sup>	SRCV or SRCVL
Cast iron	<700N/mm <sup>2</sup>	RAP or RAPL
Cast iron	<850N/mm <sup>2</sup>	SRCV or SRCVL
Stainless steel	<700N/mm <sup>2</sup>	RAP or RAPL
Stainless steel	<850N/mm <sup>2</sup>	SRCV or SRCVL
Stainless steel	>850N/mm <sup>2</sup>	CWC to CWCX
Rail track	>850N/mm <sup>2</sup>	SCRWC or SCRWCL
Tool steel	>850N/mm <sup>2</sup>	CWC to CWCX
Die Steel	>850N/mm <sup>2</sup>	CWC to CWCX

The data listed below is for reference purposes only, and indicate potential starting conditions. It is the responsibility of the site operation manager to determine correct application requirements.

Material to be cut	Cutting surface speed Meters/min	Cutter diameter/Material/RPM relationship															
		13		14		18		22		30		50		65			
		L	U	L	U	L	U	L	U	L	U	L	U	L	U		
Aluminium	60 - 90	1469	2203	1364	2046	1061	1591	868	1302	637	955	382	573	294	441		
Brass & Bronze	40 - 50	979	1224	909	1137	707	884	579	723	424	530	255	318	196	245		
Iron: cast(soft)	30 - 50	734	1224	682	1137	530	884	434	723	318	530	191	318	147	245		
cast(hard)	15 - 21	367	514	341	477	265	371	217	304	159	223	95	134	73	103		
cast(malleable)	15 - 30	367	734	341	682	265	530	217	434	159	318	95	191	73	147		
Steel: mild	24 - 30	588	734	546	682	424	530	347	434	255	318	153	191	118	147		
high tensile	3 - 5	73	122	68	114	53	88	43	72	32	53	19	32	15	24		
stainless (free cutting)	15 - 18	367	441	341	409	265	318	217	260	159	191	95	115	73	88		
stainless (heat resisting)	6 - 13	26	318	136	296	106	230	87	188	64	138	38	83	29	64		

These are only starting points. They will vary with application and work piece condition.

Material or Application Type	Feed Per Tooth (mm)
Thin Walled Workpieces Oblique Entry / Curved Surfaces Semi-Circles / Fragile Setups	.0254 / .0308 (.0762 FPT with Work Hardening Materials)
Soft / Gummy Materials	.1016 / .127
Typical / Average Applications	.0762 / .1016
Deep Holes	.1016 / .127

Difficult-to-machine materials will require reduced feed rates.

