



CUTTING AND GRINDING DISC (PTC SERIES)

PRECAUTIONS ON THE USE OF ABRASIVE GRINDING WHEELS

Always ensure that the spindle speed of the machine is no higher than the operating speed marked on the wheel.

Always visually inspect all wheels before mounting for possible damage in transit or during manipulation.

After mounting the wheel, always check that between the operating machine spindle and the blocking ring no free space is left to avoid any wobbling of the wheel. Allow newly mounted wheels to run at operating speed, with guard in place, for some seconds before cutting and grinding.

Always use operating machines that have a safety guard.

Always follow the indications marked on the wheel and check that the grinding wheel being used is the correct one for the material of your workpiece.

ATTENTION: Cutting discs must be used for cutting only!

Always use eye protection.

Stocks of grinding and cutting discs are guaranteed for maximum of 3 years as long as they are stocked into a dry room and handled with care.

If wrongly used this product can cause damage or injury to people.