


۲

BEADS & CORNER MOULDS



For stationary machines at max. recommended speeds as indicated.

trend