



230V 160A

# ARC WELDER

71090 - AW164AT SPARE PARTS DRAWING

KEY No.	PART No.	STOCK No.	DESCRIPTION	KEY No.	PART No.	STOCK No.	DESCRIPTION
1	YAW164AT-1	76989	Screw for handle	13	YAW164AT-13	77236	Nuts
2	YAW164AT-2	77005	Handle	14	YAW164AT-14	77237	Bottom bracket
3	YAW164AT-3	77028	Machine cover	15	YAW164AT-15	77238	Bottom cover
4	YAW164AT-4	77029	Top glass window	16	YAW164AT-16	77239	Hot light
5	YAW164AT-5	77030	Screw for machine cover	17	YAW164AT-17	77241	Power switch
6	YAW164AT-6	77053	Fan	18	YAW164AT-18	77244	Threaded adjuster
7	YAW164AT-7	77064	Spring clip	19	YAW164AT-19	77399	Triangle switch
8	YAW164AT-8	77107	Thermal protection	20	YAW164AT-20	77506	Cable gland
9	YAW164AT-9	77166	Transformer	21	YAW164AT-21	77563	Rubber foot
10	YAW164AT-10	77183	Insert spring	22	YAW164AT-22	77604	Spacer
11	YAW164AT-11	77229	Moving iron	23	YAW164AT-23	77672	Screw for bottom bracket
12	YAW164AT-12	77235	Upper bracket	24	YAW164AT-24	77675	Cable gland

230V 160A

# ARC WELDER

71090 - AW164AT SPARE PARTS DRAWING

